## GL: Emergency Relief – SHOPP Emergency Response Program (TIP ID – VAR170008)

Last updated with 2023 TIP Update

## FTIP BACK-UP LIST FOR SHOPP - EMERGENCY RESPONSE PROJECTS (VAR170008)

FOR 2020/2026 PROGRAM YEARS
All amounts in \$1,000

DIST	Co	Rte	PM	Location/Description	PPNO	EA	<b>Prog Code</b>	Con FY	Prior	22/23	23/24	24/25	25/26	PAED	PSE	<b>RW SUP</b>	CONSUP	RW	CON	TOTAL
	SON			Near Jenner, from 0.3 to 0.4 mile north of Myers Grade		0J300	201.131	20/21		\$0	\$0	\$0	\$0		\$2,496	\$208	\$3,137	\$243	\$15,720	\$23,910
				Road. Permanent restoration of roadway slipouts.					,		·	·		. ,	. ,	·	. ,	·	. ,	. ,
04	ALA	680		In Fremont, at the northbound offramp to Mission Boulevard. Stabilize storm damaged embankment.	2028M	0Q680	201.131	21/22	\$5,641	\$0	\$0	\$0	\$0	\$750	\$885	\$60	\$1,033	\$5	\$2,908	\$5,641
04	ALA	92		In Hayward, at the westbound connector from	2028K	0Q450	201.131	21/22	\$1,510	\$0	\$0	\$0	\$0	\$285	\$347	\$16	\$191	\$10	\$661	\$1,510
	, `	0_		northbound Route 880. Restore eroded embankment			2011.101	,	Ψ1,010	Ψ	Ψ	Ψ**	Ψ.	Ψ200	ΨΟΙΙ	Ψισ	Ψ.σ.	Ψίσ	ΨΟΟΙ	Ψ1,010
				and extend existing concrete barrier.																
	ALA	260	1.1/1.9	In the cities of Alameda and Oakland, at the Posey	2909B	2W740	201.131	21/22	\$8,550	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,050	\$0	\$6,500	\$8,550
				Tube No. 33-0106R (PM R1.1R to R1.9R) and Webster																. ,
				Tube No. 33-0106L (PM R1.1L to R1.9L). Install fuel																
				cell power supply systems to maintain safety systems in																
				the event of a fire emergency.																
04	CC	80		Near San Pablo, on El Portal Drive onramp to	2909P	3W770	201.130	21/22	\$815	\$0	\$0	\$0	\$0	\$0	\$0	\$10	\$270	\$10	\$525	\$815
				westbound Route 80. Reconstruct the damaged																
24 .		101	0.5/4.5	soundwall and concrete barrier.	2222	014/000	004.400	0.4/0.0	****	**	•••	**	40	**	**	**	4005	••	<b>***</b>	4005
04 N	MRN	101	3.5/4.7	Near Sausalito, at Richardson Bay Bridge No. 27-0010.	2909E	3W390	201.130	21/22	\$935	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$325	\$0	\$610	\$935
				Remove damaged expansion joint, repair concrete																
04 N	MDNI	1		section, and install new finger joints.  Near Stinson Beach, at 0.7 mile south of Panoramic	20341	0W130	201.131	21/22	\$2,324	\$0	\$0	\$0	\$0	\$0	\$454	\$25	\$500	\$31	\$1,314	\$2,324
U4   IVIF	VIIZIN	'		Highway. Implement permit requirements including	20343	000130	201.131	21/22	φ <b>∠</b> ,3 <b>∠</b> 4	φυ	φυ	φυ	φυ	φυ	φ454	φΖΟ	φουυ	φυι	φ1,314	φ <b>Ζ</b> ,3 <b>Ζ</b> 4
				plant establishment, noxious weed control, seed																
				collection and propagation, and biological monitoring for																
				emergency project EA 0P130.																
04 I	NAP	29	11.6/13.0	In Napa, from First Street to 0.1 mile south of Redwood	2022G	0Q820	201.131	21/22	\$18,056	\$0	\$0	\$0	\$0	\$1,437	\$1,792	\$152	\$1,228	\$44	\$13,403	\$18,056
				Road/Trancas Street. Repair culvert.					. ,	·	·			. ,	. ,	·	. ,	·	, ,	,
04 I	NAP	12	2.1/2.6	Near the city of Napa, from 1.2 miles to 0.7 mile west of	2021F	0Q690	201.131	21/22	\$2,557	\$0	\$0	\$0	\$0	\$308	\$320	\$150	\$400	\$134	\$1,245	\$2,557
				the Solano County line. Repair storm damaged slopes																
				at two locations with Rock Slope Protection (RSP) and																
				restore ditches.																
04 S0	SCL	152	10.2/10.4	In Gilroy, from Route 101 to Camino Arroyo.	2910B	3W840	201.130	21/22	\$790	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$260	\$0	\$530	\$790
				Reconstruct damaged pavement, repair light pole, sign																
				posts, and landscaping, clean drainage system, and																
0.4	001	_		remove hazardous waste.	44045	01/000	004.404	04/00	Φ0.070	Φ0	00	Φ0	Φ0	<b>#</b> 400	0040	<b>#</b> 00	<b>0045</b>	040	<b>04.004</b>	Φ0.070
04	SCL	9		In Saratoga, north of Pierce Road (PM 5.97). Install	1464D	2K280	201.131	21/22	\$2,073	\$0	\$0	\$0	\$0	\$130	\$318	\$36	\$315	\$10	\$1,264	\$2,073
04	SM	1		Rock Slope Protection (RSP) and replace culvert.  Near Half Moon Bay, at 1.1 miles north of Santa Cruz	1450	0K570	201.131	21/22	\$2,262	\$0	\$0	\$0	\$0	\$300	\$400	\$70	\$500	\$2	\$990	\$2,262
04	SIVI	'		County line. Repair slope washout by constructing a	143011	UKS/U	201.131	21/22	<b>Φ</b> Ζ,Ζ <b>0</b> Ζ	φυ	φυ	φυ	φυ	φουσ	φ400	\$70	<b>Φ</b> 300	φ∠	φ990	<b>Φ</b> Ζ,Ζ0Ζ
				soldier pile wall and upgrading the drainage system.																
				soldier pile wall and appraising the drainage system.																
04 S	SM	84		Near La Honda, at 1.2 miles north of Madera Lane	1455B	2K610	201.131	21/22	\$5,383	\$0	\$0	\$0	\$0	\$936	\$390	\$10	\$750	\$30	\$3,267	\$5,383
				(north). Repair slope washout and place Rock Slope				<u></u>	, ,,,,,,,,,	7 -	7.5	7.	, , , , , , , , , , , , , , , , , , ,	,	,	, ,	,	,	, ,,_ •.	, 2,200
				Protection (RSP) on existing embankment to prevent																
				further erosion.																
04 5	SON	101		Near Cloverdale, at 0.4 mile south of the Mendocino	1462P	2K350	201.131	21/22	\$4,685	\$0	\$0	\$0	\$0	\$840	\$413	\$128	\$459	\$225	\$2,620	\$4,685
				County line. Restore slope, rebuild damaged gutter and																
				install erosion control measures.																
04   3	SON	1	15.1/15.7	Near Carmet, from 0.1 mile to 0.7 mile north of Calle	0748R	0A021	201.131	21/22	\$8,400	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,400	\$7,000	\$0	\$8,400
	2011		45 44	Del Sol. Biological mitigation for project EA 0A020.	07.155	04055	004.45.	0.1.55	<b>A4.000</b>	**	40	**	**	**	**	**	# <b>* * * * * * * * * *</b>	<b>A</b> ( 0.5.5	**	01.000
04 5	SUN	1	15.1/15.7	Near Carmet, from 0.1 mile to 0.7 mile north of Calle Del Sol. Stormwater mitigation for project EA 0A020.	U/48S	0A022	201.131	21/22	\$1,200	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$200	\$1,000	\$0	\$1,200
						<u> </u> т	ime Extensi	on Total	\$89,091	\$0	\$0	\$0	\$0	\$7,092	\$7,815	\$865	\$13,018	\$8,744	\$51,557	\$89,091
04	ALA	580		Near Livermore, at 0.3 mile west of Stonecut Underpass	1461D			22/23	\$2,219	\$4,930	\$0	\$0	\$0	\$752			\$1,270	\$70	\$3,590	\$7,149
				(PM R4.3L). Restore eroded embankment slope in the					į	·							·			
				eastbound direction and install erosion control																
				castboaria direction and install crosson control																

April 21, 2022 1 of 2

## FTIP BACK-UP LIST FOR SHOPP - EMERGENCY RESPONSE PROJECTS (VAR170008)

FOR 2020/2026 PROGRAM YEARS
All amounts in \$1,000

Dist	Со	Rte	PM	Location/Description	PPNO	EA	Prog Code	Con FY	Prior	22/23	23/24	24/25	25/26	PAED	PSE	RW SUP	CONSUP	RW	CON	TOTAL
04	NAP	121	16.0/16.1	Near Napa, at Wooden Valley Road. Repair pavement,	2022F	0Q810	201.131	22/23	\$2,362	\$2,060	\$0	\$0	\$0	\$902	\$1,287	\$173	\$661	\$86	\$1,313	\$4,422
				replace drainage systems, and upgrade guardrail.																
04	SM	1		Near Montara, at south of 9th Street. Repair damaged	2028H	0Q670	201.131	22/23	\$833	\$1,808	\$0	\$0	\$0	\$418	\$388	\$27	\$373	\$35	\$1,400	\$2,641
				storm drain and restore eroded embankment.																
04	SM	84		Near La Honda, west of Peek-A-Boo Lane. Construct	1455C	2K640	201.131	22/23	\$1,731	\$4,057	\$0	\$0	\$0	\$1,056	\$635	\$40	\$484	\$371	\$3,202	\$5,788
				soldier pile wall, reconstruct damaged pavement, and					,	,			·	. ,	·	·	·	·	. ,	,
0.4	014	0.4		upgrade guardrail.	00004	00.400	004.404	00/00	<b>#4.700</b>	04.700	Φ0	40	40	4004	<b>#</b> 000	400	<b>#500</b>	0440	04.004	<b>#0.405</b>
04	SM	84		Near La Honda, at 0.5 mile west of Pescadero Creek Road. Repair slope washout by constructing a retaining	2032A	0Q480	201.131	22/23	\$1,733	\$4,762	\$0	\$0	\$0	\$924	\$809	\$33	\$522	\$146	\$4,061	\$6,495
				wall.																
04	SOL	505		Near Vacaville, at southbound offramp to Allendale	2021G	0Q710	201.131	22/23	\$817	\$1,276	\$0	\$0	\$0	\$317	\$402	\$98	\$385	\$50	\$841	\$2,093
				Road. Restore slope washout between offramp and																
				adjacent frontage road by placing rock slope protection.																
04	SON	116		Near Monte Rio, at 0.2 mile west of Cnopius Road.	1464F	2K360	201.131	22/23	\$3,862	\$384	\$0	\$0	\$0	\$1,775	\$1,883	\$204	\$0	\$384	\$0	\$4,246
				Repair unstable slope by constructing a retaining wall.					,				·	. ,	. ,	·	·	·		,
0.4	0011	101	0.7/40.0	(G13 Contingency)	00045	4164.40	004.404	00/00	<b>#4.500</b>	04.740	Φ0	40	40	<b>\$500</b>	00.44	<b>*</b> 0.4	<b>#</b> 000	0.1.1	04040	<b>#0.040</b>
04	SON	121		Near Schellville, from 0.2 mile to 0.8 mile north of Ramal Road. Restore structural integrity of the existing	2021D	4K140	201.131	22/23	\$1,500	\$4,719	\$0	\$0	\$0	\$528	\$941	\$31	\$668	\$11	\$4,040	\$6,219
				roadway by injecting polyurethane to densify the soil																
				below and minimizing future settlement, grind and																
				replace asphalt concrete, and rehabilitate drainage																
0.4	NAD	101	10 1/00 7	systems.	00000	00700	004.404	00/04	<b>#4.00</b> 5	40.050	<b>\$0.004</b>	40	40	<b>\$4.00</b> 5	<b>#0.050</b>	<b>#</b> 400	<b>#</b> 4.004	4000	<b>*</b> 4 0 0 4	<b>*</b> 40.404
04	NAP	121	13.4/20.7	Near Napa, from 2.8 miles north of Vichy Avenue to 1.4 miles south of Route 128 at various locations. Repair	2022D	0Q790	201.131	23/24	\$1,635	\$2,252	\$6,304	\$0	\$0	\$1,635	\$2,053	\$199	\$1,361	\$639	\$4,304	\$10,191
				and restore slope washouts with Rock Slope Protection																
				(RSP), erosion control, steel sheet piles, and drainage																
				upgrades.																
04	NAP	29		Near Calistoga, at 2.5 miles south of Lake County line.	2022H	0Q830	201.131	23/24	\$1,739	\$0	\$2,323	\$0	\$0	\$736	\$885	\$118	\$878	\$165	\$1,280	\$4,062
04	SCI	152	20 5/20 8	Stabilize storm damaged embankment.  Near Gilroy, from 0.8 mile east to 1.1 miles east of San	2031M	3Q650	201.131	23/24	\$583	\$581	\$2,245	\$0	\$0	\$583	\$492	\$89	\$556	\$168	\$1,521	\$3,409
04	SCL	132	20.3/20.6	Felipe Road. Stabilize slope with Rock Slope Protection		30000	201.131	23/24	φυου	φυσι	φ2,245	φυ	φυ	φυου	<b>Φ492</b>	фов	φυυσ	φ100	φ1,521	φ3,409
				(RSP), erosion control, and drainage upgrades.																
												* -			4		*			
04 5	SON	116		Near Jenner, at 1.1 miles east of Route 1. Permanent	2031S	0AA63	201.131	23/24	\$1,130	\$780	\$4,119	\$0	\$0	\$1,130	\$710	\$70	\$710	\$656	\$2,753	\$6,029
				restoration of slope by reconstructing culvert wingwalls and placing Rock Slope Protection (RSP).																
				and placing react clope i retestion (rear ).																
04	SON	1		Near Jenner, from 0.3 to 0.7 mile north of Myers Grade	2911P	0J301	201.131	23/24	\$0	\$1,010	\$5,972	\$0	\$0	\$0	\$1,000	\$10	\$2,800	\$0	\$3,172	\$6,982
				Road. Mitigation project for EA 0J300 for plant																
04	MRN	1		establishment and erosion control.  Near Muir Beach, at 0.6 mile south of Pacific Way.	2006H	3AA50	201.131	25/26	\$1,054	\$0	\$1,934	\$0	\$6,385	\$1.05 <i>1</i>	\$1,729	\$205	\$1,520	\$39	\$4,826	\$9,373
04	IVIIXIN	١.		Repair and extend retaining wall, replace culvert and	290011	37730	201.131	23/20	φ1,054	ΨΟ	ψ1,954	ΨΟ	φυ,303	ψ1,054	ψ1,129	Ψ203	ψ1,520	ψυθ	ψ4,020	ψ9,575
				guardrail, and repair pavement.																
04	MRN	101		In Corte Madera, from 0.4 mile to 0.6 mile north of	2032M	2AA30	201.131	25/26	\$714	\$0	\$993	\$0	\$3,541	\$714	\$964	\$29	\$793	\$36	\$2,712	\$5,248
				Route 131 (Tiburon Boulevard). Restore slope, regrade																
				unlined ditch, and install erosion control measures.																
04	NAP	128		Near Saint Helena, at 1.2 miles east of Chiles Pope	2906G	4AA30	201.131	25/26	\$1,539	\$0	\$0	\$1,904	\$7,168	\$1,539	\$1,829	\$75	\$1,813	\$44	\$5,311	\$10,611
		-		Valley Road. Construct retaining wall, rehabilitate					, , , , , ,			, , , , , ,	. ,	, ,,,,,,,,	, ,==3		. ,		,	
				drainage system, and install erosion control to stabilize																
				slope.					6440 = 40	<b>ADD 646</b>	<b>#00.00</b>	<b>#4.004</b>	647.001	604 455	A05 40 1	AC 074	<b>607.040</b>	644.644	<b>***</b>	6404.040
					SHOPP -	Emerge	ncy Respons	e TOTAL	\$112,542	\$∠8,619	<b>\$</b> 23,890	\$1,904	\$17,094	<b>\$∠1,155</b>	\$∠5,184	\$2,371	\$27,812	\$11,644	<b>\$95,883</b>	\$184,049

April 21, 2022 2 of 2